


GLP Firmware Change Log



impression X5 (X5-19) / Firmware Log / 01/11/2023


Below you will find the history of all fixture firmware versions since the release of the device. Please note the respective information on functional changes, extensions, optimizations, etc. Even if it is our goal to develop firmware updates without relevant performance changes, it can always happen that optimizations or bug fixes can affect the device performance. Please read the note on "INFO" as a matter of urgency.

We strongly advise that firmware updates be carried out on individual replacement devices first. Likewise, updates should never be carried out shortly before an important use of the device. If in doubt, speak to your GLP Service Team.

- 11 Jan 2023 / Main changes from V0.14.4 to V0.14.5
- 22 Dec 2022 / Main changes from V0.12.6 to V0.14.4 / BL0.14.4
- 11 Nov 2022 / iQ.Mesh Update to Version 5.0.26
- 19 Aug 2022 / Main changes from V0.12.4 to V0.12.6
- 13 May 2022 / Main changes from V0.9.5 to V0.12.4
- 12 Mar 2022 / V0.9.5 (Fieldtest)

11 Jan 2023 / Main changes from V0.14.4 to V0.14.5	
VERSION DETAILS	<ul style="list-style-type: none">• N/A
BUG FIXES	<ul style="list-style-type: none">• Fixed bug in dimmer curve in RGBL - ColorMix Mode
UPDATE PROCESS	<p>If fixtures are on V0.12.6 or earlier an iQ.Mesh Update has to be performed via the iQ.Mesh App. Afterwards 2 files have to be uploaded via DMX/RS485. First the new Bootloader, second, the Main application. Please take care that fixtures don't lose power between the two updates. (1, 2, 3) For the mesh update please refer to the separate mesh update manual.</p> <p>If fixtures are already on V0.14.4 only the main application V0.14.5 has to be uploaded. (3)</p> <p>1.) Mesh Update to Version 5.0.26</p> <p>2.) Upload: impression-X5_0.14.5_BOOTDMX.bin</p> <p>This has to be done via DMX, D3Prog, daisy chain. To get all drivers internally updated please wait 5 minutes after this update before you proceed with step 2. During Step1 the fixtures display can go off. Don't worry. Just wait the specified 5 minutes. The display will go On after step 2 again.</p> <p>3.) Upload: impression-X5_0.14.5_DMX.bin</p> <ul style="list-style-type: none">• When importing the bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer. <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX</p>
INFO	<p>⚠ This update is show critical as pattern, dimming, colormix and shutter behavior is changed and should not be done on site. V0.12.4 and 0.12.6 is stable, still.</p>

GLP Firmware Change Log



impression X5 (X5-19) / Firmware Log / 01/11/2023

VERSION PACKAGE	impression-X5_0.14.5_DMx.bin impression-X5_0.14.5_BOOTDMX.bin
-----------------	------------------------------------------------------------------

22 Dec 2022 / Main changes from V0.12.6 to V0.14.4 / BL0.14.4

VERSION DETAILS	<ul style="list-style-type: none">• Added additional pattern• Improved RDM, added RDM Identify• Implemented "No-Signal" Scene• Implemented Manual DMX• Implemented Fan Modes High, Medium and Low• Implemented Hibernation via DMX• Implemented various test modes
BUG FIXES	<ul style="list-style-type: none">• Fixed bugs in dimmer curve• First light output at Dimmer DMX 001
UPDATE PROCESS	<p>Two files have to be uploaded via DMX/RS485, first the new Bootloader, second, the Main application. Please take care that fixtures don't lose power between the two updates.</p> <p>1.) Upload: impression-X5_0.14.4_BOOTDMX.bin</p> <p>This has to be done via DMX, D3Prog, daisy chain. To get all drivers internally updated please wait 5 minutes after this update before you proceed with step 2. During Step1 the fixtures display can go off. Don't worry. Just wait the specified 5 minutes. The display will go On after step 2 again.</p> <p>2.) Upload: impression-X5_0.14.4_DMx.bin</p> <ul style="list-style-type: none">• When importing the bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer. <div style="background-color: #ffe6e6; padding: 5px;"><p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX</p></div>
INFO	<p>⚠ This update is show critical as pattern, dimming, colormix and shutter behavior is changed and should not be done on site. V0.12.4 and 0.12.6 is stable, still.</p>
VERSION PACKAGE	impression-X5_0.14.4_DMx.bin impression-X5_0.14.4_BOOTDMX.bin

GLP Firmware Change Log




impression X5 (X5-19) / Firmware Log / 01/11/2023

11 Nov 2022 / iQ.Mesh Update to Version 5.0.26	
VERSION DETAILS	Mandatory Update of the iQ.Mesh Version via the iQ.Service App
VERSION PACKAGE	impression-X5_0.12.6_DMx.bin

19 Aug 2022 / Main changes from V0.12.4 to V0.12.6	
VERSION DETAILS	Added support for new display type
BUG FIXES	--
UPDATE PROCESS	<p>One file has to be uploaded via DMX/RS485</p> <ol style="list-style-type: none">1. Upload: impression-X5_0.12.6_DMx.bin <p>When importing the bin file to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer.</p> <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.</p>
INFO	<p>Update is not necessary on older fixtures.</p> <p>V0.12.4 is stable.</p> <p>Update is not show critical</p>
VERSION PACKAGE	impression-X5_0.12.6_DMx.bin

GLP Firmware Change Log



impression X5 (X5-19) / Firmware Log / 01/11/2023

13 May 2022 / Main changes from V0.9.5 to V0.12.4	
CHANGES	<ul style="list-style-type: none">• Changed DMX Modes to final version• Changed Mode5, this mode comes now without color channel• Changed Zoom direction, zoom 255 is now wide• Changed Pan Tilt range default to normal angle and added option to choose between 540° pan (normal) and extended pan range 650°• Changed and finished pattern and pattern channel layout• Added: RGBL Color Mode• Added: Battery mode• Added: "No-Signal: Hold"• Added: Pan Motor is disabled when working in the menu
BUG FIXES	Fixed: Light Output During Reset.
UPDATE PROCESS	<p>Two files have to be uploaded in sequence via DMX/RS485, one after the other:</p> <ol style="list-style-type: none">1. Upload: impression-X5_0.12.4_BOOTDMX.bin After the update of the new Bootloader is finished please wait about 30 seconds before the second step below2. Upload: impression-X5_0.12.4_DMx.bin When importing the 2 bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the files to the programmer. <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.</p>
INFO	<p>Update is show critical!! Anything programmed and running with V0.9.5 should stay on 0.9.5 if it should work and look the same as before !</p>
VERSION PACKAGE	impression-X5_0.12.4_DMx.bin; impression-X5_0.12.4_BOOTDMX.bin

12 Mar 2022 / V0.9.5 (Fieldtest)	
INFO	First Release
VERSION PACKAGE	impression-X5_0.9.5_DMx.bin