

GLP Firmware Change Log



impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023

Below you will find the history of all fixture firmware versions since the release of the device. Please note the respective information on functional changes, extensions, optimizations, etc. Even if it is our goal to develop firmware updates without relevant performance changes, it can always happen that optimizations or bug fixes can affect the device performance. Please read the note on "INFO" as a matter of urgency.

We strongly advise that firmware updates be carried out on individual replacement devices first.

Likewise, updates should never be carried out shortly before an important use of the device. If in doubt, speak to your GLP Service Team.

02 Jun 2023 / Main changes from V1.0.1 to V1.1.3

NEW FEATURES & IMPROVEMENTS	<ul style="list-style-type: none">Renamed DMX Mode 5 to Multipix Compressed RGBAdded new DMX Mode 6: Multipix Compressed RGBLAdded beta Firmware support. Version number has -beta appended and the screen background is purple.
BUG FIXES	<ul style="list-style-type: none">Zoom, Pan and Tilt can freeze (very seldom) because of bus transmission issuesGamma correction was accidentally applied to background layer pixels in any ColorMix Mode. Gamma correction should only be applied in ColorMix Mode: RGB. This resulted in different color outputs when the same color values were applied to foreground and background layer.Lightning shutter effect was not working correctly
UPDATE PROCESS	<p>Fixtures need 1 update, if V1.0.1 or higher is installed already.</p> <p>Via D3Prog (RS485/DMX) :</p> <ol style="list-style-type: none">Update the Main Application V 1.1.3 via DMX/RS485 via D3Prog (impression-X5_1.1.3_DMX.bin) <p>Optional via iQ.Service App (no Login needed) :</p> <p>Change the Control Protocol in the Fixtures Protocol Setup Menu to iQ.Mesh, or via DMX Control Channel to iQ.Service Connect: DMX 012-013 (4,7% - 5,1%)</p> <ol style="list-style-type: none">Update the Main Application V 1.1.3 <p>Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX!</p>
INFO	<p>⚠ This update is show critical as the color mix bug (Gama correction bug) is solved and should not be done on site, especially when background colors are programmed and in use.</p>
VERSION PACKAGE	impression-X5_1.1.3_DMX.bin (provided via website as download and iQ.Service App)

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023




23 Mar 2023 / **Main changes from V0.14.5 to V1.0.1**

VERSION DETAILS	<ul style="list-style-type: none">• Updated Color Calibration (4.5.0) (via iQ.Service App)• Added iQ.Gamut Color selection: Full, Rec.2020, Rec709, DCIP3.65• Added: Dimmer Curves Linear and S-Curve• Added and adjusted Fan Modes. Regulated Mode will be much more quite and turn off all fans when LEDs off and the temperature allows fans off.• Added: PWM Settings• Added: Hibernate : Caution, fixture needs wakeup via DMX or power-cycle to leave hibernate.• Added: Advanced Service Menu: Job Offsets (Pan, Tilt, Zoom)• Added: RDM : Set Factory Default Settings• Added: RDM : Get Fixture Serial Number
BUG FIXES	<ul style="list-style-type: none">• Fixed: Color Mixing: Previous Color Calibration version could lead to color and intensity jumps• Fixed: Increased Zoom Speed in Normal Performance Mode back to normal speed (faster).• Fixed: iQ.Mesh: Activate iQ.Mesh via DMX Control Channel, as long as the DMX Slot (012-013) is selected. When the slot is not selected anymore a 5 minute timeout starts after which the iQ.Mesh module will fall asleep.• Fixed: Update via iQ.Service App works fast as supposed to be. Unfortunately after this update ..• Changed: No Signal Mode: Default is now DMX-Hold

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023




UPDATE PROCESS	<p>Fixtures need 4 updates. One after the other.</p> <p>Via D3Prog / RS485/ DMX</p> <ol style="list-style-type: none">1. Update the Main Bootloader V1.0.0 via DMX/RS485 via D3Prog (impression-X5_1.0.0_BOOTDMX.bin)2. Update the Main Application V 1.0.1 via DMX/RS485 via D3Prog (impression-X5_1.0.1_DMX.bin) <p>Change the Control Protocol in the Protocol Setup Menu to iQ.Mesh: Update via iQ.Service App:</p> <ol style="list-style-type: none">3. Update the iQ.Mesh Version to V5.0.314. Update the Color Calibration to V4.5.0 <p>If you have fixtures below version 0.14.5 or just an older set bootloaders: it could occur that after the BL update (step 1) the fixture needs about 5 minutes to prepare all internal updates with its display off. Please do allow the fixture these 5 minutes before proceeding with the main update step 2, while display is off still. The display will come back automatically during step 2.</p> <p>The first two updates have to be done via DMX, D3Prog, daisy chain. When importing the bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer.</p> <div><p>Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX for step 1 and step 2 and iQ.Mesh (iQ.Data) for step 3 and step 4 . Do set to iQ.Mesh via Protocol setup menu, only! All fixture settings will perform a reset to factory defaults after the main application update (step 2), if updateing from 0.X.X to 1.X.X After step 4 remember to change back the Protocol Data In to DMX.</p></div>
INFO	<p> This update is show critical as pattern, dimming, colormix and shutter behavior is changed and should not be done on site.</p>
VERSION PACKAGE	<p>impression-X5_1.0.0_BOOTDMX.bin (provided via website/download) impression-X5_1.0.1_DMX.bin (provided via website/download) iQ.Mesh V5.0.31 (included in iQ.Service App V1.4.2) ColorCalibration V4.5.0 (included in iQ.Service App V1.4.2)</p>

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023



11 Jan 2023 / **Main changes from V0.14.4 to V0.14.5**


VERSION DETAILS	<ul style="list-style-type: none">• N/A
BUG FIXES	<ul style="list-style-type: none">• Fixed bug in dimmer curve in RGBL - ColorMix Mode
UPDATE PROCESS	<p>If fixtures are on V0.12.6 or earlier an iQ.Mesh Update has to be performed via the iQ.Mesh App. Afterwards 2 files have to be uploaded via DMX/RS485. First the new Bootloader, second, the Main application. Please take care that fixtures don't loose power between the two updates. (1, 2, 3) For the mesh update please refer to the separate mesh update manual.</p> <p>If fixtures are already on V0.14.4 only the main application V0.14.5 has to be uploaded. (3)</p> <p>1.) Mesh Update to Version 5.0.26</p> <p>2.) Upload: impression-X5_0.14.5_BOOTDMX.bin</p> <p>This has to be done via DMX, D3Prog, daisy chain. To get all drivers internally updated please wait 5 minutes after this update before you proceed with step 2. During Step1 the fixtures display can go off. Don't worry. Just wait the specified 5 minutes. The display will go On after step 2 again.</p> <p>3.) Upload: impression-X5_0.14.5_DMX.bin</p> <ul style="list-style-type: none">• When importing the bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer. <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX</p>
INFO	<p> This update is show critical as pattern, dimming, colormix and shutter behavior is changed and should not be done on site. V0.12.4 and 0.12.6 is stable, still.</p>
VERSION PACKAGE	<p>impression-X5_0.14.5_DMX.bin impression-X5_0.14.5_BOOTDMX.bin</p>

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023




22 Dec 2022 / Main changes from V0.12.6 to V0.14.4 / BL0.14.4

VERSION DETAILS	<ul style="list-style-type: none">• Added additional pattern• Improved RDM, added RDM Identify• Implemented "No-Signal" Scene• Implemented Manual DMX• Implemented Fan Modes High, Medium and Low• Implemented Hibernation via DMX• Implemented various test modes
BUG FIXES	<ul style="list-style-type: none">• Fixed bugs in dimmer curve• First light output at Dimmer DMX 001
UPDATE PROCESS	<p>Two files have to be uploaded via DMX/RS485, first the new Bootloader, second, the Main application. Please take care that fixtures don't lose power between the two updates.</p> <p>1.) Upload: impression-X5_0.14.4_BOOTDMX.bin</p> <p>This has to be done via DMX, D3Prog, daisy chain. To get all drivers internally updated please wait 5 minutes after this update before you proceed with step 2. During Step1 the fixtures display can go off. Don't worry. Just wait the specified 5 minutes. The display will go On after step 2 again.</p> <p>2.) Upload: impression-X5_0.14.4_DMX.bin</p> <ul style="list-style-type: none">• When importing the bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer. <div><p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX</p></div>
INFO	<p> This update is show critical as pattern, dimming, colormix and shutter behavior is changed and should not be done on site. V0.12.4 and 0.12.6 is stable, still.</p>
VERSION PACKAGE	<p>impression-X5_0.14.4_DMX.bin impression-X5_0.14.4_BOOTDMX.bin</p>

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023



11 Nov 2022 / iQ.Mesh Update to Version 5.0.26

VERSION DETAILS	Mandatory Update of the iQ.Mesh Version via the iQ.Service App
VERSION PACKAGE	impression-X5_0.12.6_DMX.bin

19 Aug 2022 / Main changes from V0.12.4 to V0.12.6

VERSION DETAILS	Added support for new display type
BUG FIXES	--
UPDATE PROCESS	<p>One file has to be uploaded via DMX/RS485</p> <p>1. Upload: impression-X5_0.12.6_DMX.bin</p> <p>When importing the bin file to a D3Prog make sure that you choose the file type „BIN“ before uploading the file to the programmer.</p> <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.</p>
INFO	<p>Update is not necessary on older fixtures.</p> <p>V0.12.4 is stable.</p> <p>Update is not show critical</p>
VERSION PACKAGE	impression-X5_0.12.6_DMX.bin

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023



13 May 2022 / Main changes from V0.9.5 to V0.12.4

CHANGES	<ul style="list-style-type: none">• Changed DMX Modes to final version• Changed Mode5, this mode comes now without color channel• Changed Zoom direction, zoom 255 is now wide• Changed Pan Tilt range default to normal angle and added option to choose between 540°pan (normal) and extended pan range 650°• Changed and finished pattern and pattern channel layout• Added: RGBL Color Mode• Added: Battery mode• Added: "No-Signal: Hold"• Added: Pan Motor is disabled when working in the menu
BUG FIXES	Fixed: Light Output During Reset.
UPDATE PROCESS	<p>Two files have to be uploaded in sequence via DMX/RS485, one after the other:</p> <ol style="list-style-type: none">1. Upload: impression-X5_0.12.4_BOOTDMX.bin After the update of the new Bootloader is finished please wait about 30 seconds before the second step below2. Upload: impression-X5_0.12.4_DMx.bin When importing the 2 bin files to a D3Prog make sure that you choose the file type „BIN“ before uploading the files to the programmer. <p>The fixtures can be updated daisy chain via DMX/RS485. Please make sure that no other DMX receivers or consoles are active on the line and fixtures Control Protocol is set to DMX.</p>
INFO	<p>Update is show critical!!! Anything programmed and running with V0.9.5 should stay on 0.9.5 if it should work and look the same as before !</p>
VERSION PACKAGE	impression-X5_0.12.4_DMx.bin; impression-X5_0.12.4_BOOTDMX.bin

12 Mar 2022 / V0.9.5 (Fieldtest)

INFO	First Release
------	---------------

GLP Firmware Change Log

impression X5 (X5-19) / impression X5 Firmware Log V1.1.3 / 06/02/2023



VERSION PACKAGE	impression-X5_0.9.5_DMX.bin
-----------------	-----------------------------